General Environmental Incident Summary

Responsible Party: Unkr	nown	112 0930	DEM INCIDENT NO.	
Date Incident: 8/23/2012 Time Inc		: 0800	Duration:	
County: Burleigh	<i>Twp:</i> 139 <i>Rr</i>	ng: 80 Sec .	: 30 Qtr :	
Lat: 46.83073 Long: -100.82440 Method: Derived from TRS				
Location Description: Sheen check between Memorial and Railroad Bridges				
Submitted By: Al Hunt		Affiliation:		
Address:				
City:		State:	Zip:	
Received By:				
Contact Person:				
Unknown Bismarck, ND				
Distric	iick, ND			
Distance Nearest Occup	ied Building:			
Type of Incident: Comple	aint			
Description of Released	Contaminant: Unknown	own		
Volume Spilled:			Ag Related: No	
EPA Extremely Hazardo	us Substance: Unkno	own	Reported to NRC: Unknow	νn
Cause of Incident:				
Complaint of sheen on Mis	ssouri River			
Diele Fredricken				
Risk Evaluation:				
		A.C		
# of Fatalities: # of Injuries:		Affected Med	<i>lium:</i> 02 - water	
Potential Environmental	Impacts:			
Action Taken or Planne	d:			
Action Taken of Trainlet	4.			
Wastes Disposal Location	on:			
Agencies Involved:				

Updates

Date: 8/23/2012 Status: Inspection Author: Hunt, Al

Updated Volume:

Notes:

Walked western shoreline with Peter. No sheen was seen on the water. A little bio-sheen, but not gas or diesel. Peter contacted the report sender, explained it was bio-sheen.

Date: 8/23/2012 Status: Inspection Author: Roberts, Kris

Updated Volume:

Notes:

Assigned to Al Hunt for investigation.